

---

Электро-эрозионный станки

Программирование


---

---

Электро-эрозионный станки

Прошивные


Проволочно-вырезные



# Прошивные электро-эрозионные станки




## Элементы станка







## Технологии

The machining current is optimally controlled according to the change in the electrical discharge area as machining proceeds.



- Rough machining time is reduced.
- Eliminate abnormal electrode wear and arcing.



## Технологии



- **Eliminate gas and chips that collect alongside the electrode.**
- **Stabilize machining and reduce rough machining time.**
- **Effective for deep machining.**

# Технологии


## Rough machining time depends on jump Speed







## Технологии



**Machining condition and jump motion are optimally controlled at chamfer ( lead in ), thereby she reaches a stable machining state quickly.**

## Примеры деталей




**Work-piece material:** NAK80  
**Machining depth:** 20mm  
**Rate of high speed jump:** 5m/min  
**Surface finish:** 5 $\mu$ mRy



**Electrode:** Gr(EX70) **200x50mm**  
**Width of Rib:** 1mm  
**Number of electrode:** 2  
**Electrode reduction:** 0.15mm

	conventional	Super Spark	Super Spark II
Overall	44H 52min	32H 22min (-28%)	27H 52min (-38%)
Roughing	26H 32min	14H 02min (-47%)	14H 02min (-47%)
Finishing	18H 20min	18H 20min (-0%)	13H 50min (-25%)

## Примеры деталей



**Work-piece material:** NAK80  
**Machining depth:** 20mm  
**Rate of high speed jump:** 5m/min  
**Surface finish:** 5 $\mu$ mRy



**Electrode:** Gr(EX70) **90×30mm**  
**Width of Rib:** 1mm  
**Number of electrode:** 2  
**Electrode reduction:** 0.15mm

**conventional**



**Super Spark**



**Super Spark II**

Overall **17H 20 min**

**11H 22min (-34%)**

**9H 12min (-47%)**

Roughing **11 H**

**5H 22min (-51%)**

**5H 22min (-51%)**


Finishing **6H 20min**

**6H (-5%)**

**3H 50min (-39%)**

---


## Примеры деталей



## Примеры деталей

No pin holes on the surface.

Magnification rate : 50




(  $0.21\mu\text{m Ra}$ ,  $1.70\mu\text{mRy}$  )




(  $0.18\mu\text{mRa}$ ,  $1.34\mu\text{mRy}$  )

## Different of grain diameter.

Magnification rate :  
400




(  $0.21\mu\text{m Ra}$ ,  $1.70\mu\text{mRy}$  )



(  $0.18\mu\text{mRa}$ ,  $1.34\mu\text{mRy}$  )

Reducing polishing time ... Superior surface finishes can be achieved with a graphite electrode.


Tip width : 0.5mm



A multi-rib for mobile phone machined by V56

Surface finish : Ra 0.16um

Electrode : Poco EDM3  
Electrode reduction : 0.1mm  
Number of electrodes : 2  
Machining depth : 4.0 mm  
Work-piece : HPM50  
Machining time : 4hr30min.








---

# Проволочно-вырезные электро-эрозионные станки






# Элементы станка




SP43/SP64

**V-Flat Guide**



**Round Guide**



UPH-2/UPJ-2



U32j/U53j/U53Tj



U86





W32FB/W53FB

# Элементы станка

V-guide (Wire guide)

Flat-guide (Clamp guide)



E  
n  
e  
r  
g  
y  
z  
i  
n  
g  
p  
l  
a  
t  
e

Close/Unclose

# Элементы станка

Energizing plate

V guide




Round guide

(For  $\varphi 0.07, 0.1, 0.15, 0.2, 0.25\text{mm}$ )




Jet nozzle

( $\varphi 0.5, 0.7, 1.0, 1.5\text{mm}$ )



# Технологии


Unstable burning condition




Stable burning condition

## Технологии

V-corner / OFF




V-corner / ON



**In the 1<sup>st</sup> pass, wire feed delay ( corner washout ) is compensated for in real time so that the same amount of material can be removed consistently in the 2<sup>nd</sup> pass.**



Технологии



## Технологии



**Total machining time : 14 hrs / 9 pieces**


**Material : SKD11(JIS) / Similar to 1.2379 (DIN)**

**Used wire :  $\varnothing 0.2$ Bs / U32j**

**Surface roughness :  $1.0\mu\text{mRy}$  /  $0.09\mu\text{mRa}$**

**Clearance :  $2.5\mu\text{m}$**

**A key technology to achieve superior straightness when cutting a thick work-piece is to minimize the error as much as possible in the 1<sup>st</sup> pass.**




Технологии



Stable  
machining

Faster machining  
speed



Better machining  
performance



# Технологии



## Технологии



**Two sensors installed separately for upper and lower head monitor the flushing condition so that this can provide optimal cutting speed and prevent wire breaks.**




No	Description	Function and format
G00	Быстрый ход	G00 (X_) (Y_) (U_) (V_);
G01	Лин. интерпол.	G01 (X_) (Y_) (U_) (V_);
G02	Круговая интерполяция по часовой стрелке	G02 (X_) (Y_) (I_) (J_); X_Y_: End point coordinates of arc I_J_: Incremental distance to arc center from start point  G02 (X_) (Y_) (R_); X_Y_: End point coordinates of arc R_: Radius of arc (R negative is for arc exceeding 180°)
G03	Круговая интерполяция против часовой стрелки	G03 (X_) (Y_) (I_) (J_); X_Y_: End point coordinates of arc I_J_: Incremental distance to arc center from start point  G03 (X_) (Y_) (R_); X_Y_: End point coordinates of arc R_: Radius of arc (R negative is for arc exceeding 180°)
G40	Отмена корр.	G40 G01 (X_) (Y_);
G41	Коррекция на радиус слева	G41 G01 D_ (X_) (Y_); D = offset value D0 – D9: Indirect offset command D10 – D9999: Direct command of offset amount D0. – D9.999: Direct command of offset amount Note: Negative offset values are allowed
G42	Коррекция на радиус справа	G42 G01 D_ (X_) (Y_); D = offset value D0 – D9: Indirect offset command D10 – D9999: Direct command of offset amount D0. – D9.999: Direct command of offset amount Note: Negative offset values are allowed



G50	Отмена конуса	G50 G01 (X_) (Y_);
G51	Обработка конуса слева	G51 T_ (X_) (Y_); T = Taper value Degree → 3° ..... T3.0 Deg Min Sec → 1°25' 10" ..... T12510 Note: For input of Deg Min Sec values, the TAPER DMS button on the OTHERS page must be enabled.
No	Description	Function and format
G52	Обработка конуса справа	G52 T_ (X_) (Y_); T = Taper value Degree → 3° ..... T3.0 Deg Min Sec → 1°25' 10" ..... T12510 Note: For input of Deg Min Sec values, the TAPER DMS button on the OTHERS page must be enabled
G500 G54	Система координат	G501G55; Valid WCS G500-G515 & G54-G61 There are a total of 128 different user definable WCS.

No	Description	Function and format
M00	<b>Безусловный останов</b>	M00; G1 (X_) (Y_) M00;
M01	<b>Условный останов</b>	M01; G1 (X_) (Y_) M01; Optional Stop can be selected to ignore the stop by turning off the OPTIONAL STOP button on the OTHERS page.
M06	<b>Заправка проволоки</b>	M06; G00 (X_) (Y_) M06;
M07	<b>Обрезка проволоки</b>	M07; G01 (X_) (Y_) M07;
M17	<b>Включение генератора</b>	M17; The M17 must precede every M06 to turn ON machining power.
M30	<b>Конец програм.</b>	M30;
M98	<b>Вызов подпрограммы</b>	M98 (O_) (P_) (R_) (B_); O : Subprogram Operation number to be called (O number) P : Subprogram sequence no. to be called (N number) R : Repeat times for calling (default is 1) B : Number of program blocks (lines) to be executed after execution of repeat time Note: O and P cannot be omitted at the same time
M99	<b>Конец подпрограммы</b>	M99; M99 (P_) (R_); P : Returns to sequence no. specified by P after execution of a subprogram called by M98 R : Changes R (repeat times) specified by M98



Program


Explanation

%	
O0100	*Operation Number
(Die Cavity 1/2004)	*Program Names & Comments
(Reference Dimensions 1.000 x 0.500)	
G90	*Absolute Position Mode
G500 G54	*WCS Callout
G0 X0. Y0. M06	*Rapid Position to Start Point and thread wire
M17	*Turn Machining Power On (Auto-fills tank)
E1073 D0.0063	*Change Power setting (E-code) and Offset value
G41 G1 X-.25	*Turn Wire Comp Left ON and Machine to X Position
Y-.48438	*Straight Line Machining
G3 X-.23438 Y-.5 I.01563	*CCW Radius Machining
G1 X.21875	*Straight Line Machining
G3 X.25 Y-.46875 J.03125	*CCW Radius Machining
G1 Y.4375	*Straight Line Machining
G3 X.1875 Y.5 I-.0625	*CCW Radius Machining
G1 X-.125	*Straight Line Machining
G3 X-.25 Y.375 J-.125	*CCW Radius Machining
G1 Y.1	*Straight Line Machining
M01	*Optional Stop
Y0.	*Straight Line Machining
G40 X0.	*Straight Line machining and Cancel Wire Comp
M07	*Cut Wire
M30	*End Program
%	

Program Plane: 0.00000

Sub Plane: 0.50000

Machine Z: Z position



```
%  
O0100  
(Die Cavity 1/2004)  
(Reference Dimensions 1.000 x 0.500)  
G90  
G500 G54  
G0 X0. Y0. M06  
M17  
E1073 D0.0063  
G41 G52 G1 X-.25 T9.5  
Y-.48438  
G3 X-.23438 Y-.5 I.01563  
G1 X.21875  
G3 X.25 Y-.46875 J.03125  
G1 Y.4375  
G3 X.1875 Y.5 I-.0625  
G1 X-.125  
G3 X-.25 Y.375 J-.125  
G1 Y.1  
M01  
Y0.  
G40 G50 X0. T0.  
M07  
M30  
%
```

```
*Operation Number  
*Program Names & Comments  
  
*Absolute Position Mode  
*WCS Callout  
*Rapid Position to Start Point and thread wire  
*Turn Machining Power On (Auto-fills tank)  
*Change Power setting (E-code) and Offset value  
*Wire Comp Left, Taper Right, Machine X Position, Taper Value  
*Straight Line Machining  
*CCW Radius Machining  
*Straight Line Machining  
*CCW Radius Machining  
*Straight Line Machining  
*CCW Radius Machining  
*Straight Line Machining  
*CCW Radius Machining  
*Straight Line Machining  
*Optional Stop  
*Straight Line Machining,  
*Cancel Comp, Cancel Taper, Straight Line machining, Taper 0  
*Cut Wire  
*End Program
```