

Смазочно-охлаждающие жидкости (СОЖ)

- Введение :
 - Что такое СОЖ
 - Объем рынка
 - Предприятия-потребители
 - Конкуренты
- Металлообработка – типы операций
- Функции СОЖ, типы СОЖ
- Продукция Шелл
- Поставка

Shell Metal Working



Назначение СОЖ

- **Обеспечивать охлаждение, смазку и защиту инструмента и обрабатываемой поверхности**

Shell Metal Working



**Íáúái ðúíêà 50000 -
100000 ò**

**Íòðááëáíèá ïðïîûøëáííãâ ïðáäïðèýòèý ïò
...êã äî 5000 òíí**

Shell Metal Working



Îòðàñëè ìðîîûøëáíîñòè -îòðááèòáëè ÑÎÆ

- Àâòîîáèëüíàÿ

- Îäøèííèèâàÿ

- Îòîðíóâ ìðáäîðèÿòèÿ

- Ìàøèííòðèèòáëèíóâ ÷àâíâó

- Ëðáóâ ìðáäîðèÿòèÿ ñî ñòàí÷-íó

íáðóáíâàíèàì äèÿ íáðááòèè ìàòáëèâ

Shell Metal Working



Êîîéóðáíòû Øåëë

- **Castrol**
- **Stuart**
- **Fuchs**
- **Quaker**
- **Blazer**

Shell Metal Working



Ñèëüíûâ ñòíðííû Øåëë

- *Đàçâòâëáíàÿ ñåòü äèñòðèáóðîðíâ*
- *Îèèæáíà ñõàìà ïññòàâíê ÷åðç òèíñèèé ñêèää*
- *Óíèâðñàèüíúé ïðòòåüè ïðíäóóèâ*

Shell Metal Working



İđiöãññû îáðàáíòèè ìàòàëëîâ


Îñîîáíûâ ïđiöãññû

- Đàçàíèá (îáðàçîâàíèá ñòðóæèè)
- ÎÄ
- Ýëâèòđíýđîçèîíîâÿ îáðàáíòèè ìàòàëëîâ
- Çàùèòà îò èíđđîçèè
- Çàêàëëèà
- Î÷èññèèà


Shell Metal Working



ÎĐ âêëþ÷ààò â ñâáÿ:





Ôðàçåðíâáíèà




Ñâáððèâíèà


Ñòðíâáíèà



Đàçââðòèà



Òíèàðí.íâðâáíòèà Øèèòíâáíèà



Shell Metal Working




Íáðàçíâàíèå ñòðóæèè

- Íáðàçíâàíèå ñòðóæèè - èàè ñäâèã èàðò â èíèíäå (òðåíèå ñêèëüæåíèë)
- Â çàâèñèííîè ìò ìàòðèàëà è èà÷åííà ìåòðîðííîè èãðàðò ðèëü ìàðìàòòó :
 - ñêèðíîó ðåçàíèëü V
 - ìåòàë èíòðóíèà
 - óãíè ðåçàíèëü
 - æåóáèà ðåçàíèëü T

Shell Metal Working



Íáðàçîâàíèà ñòðóæèè



Shell Metal Working



Íàçíà÷áíèå ÑÎÆ

- **Reduce friction and wear thus (See lubrication regimes):**
 - Improving tool life and surface finish
 - Reducing forces and energy consumption
- **Cool the cutting zone, thus reducing temperature and distortion. (See diagram for typical temperature distribution.)**
- **Wash away the chips from the cutting zone**
- **Protect the newly machined surfaces from corrosion**

Shell Metal Working




Íàçíà÷áíèà ÑÎÆ

Lubrication Regimes


Full film Lubrication

Boundary conditions


EP conditions



Modest load, complete separation of surfaces. Load completely supported by fluid.



Higher load, oil film almost squeezed out. Additional support needed from polar fatty oils / additives.



Very high load, high friction, collision of asperities. EP additives prevent welding.


Shell Metal Working



Íàçíà÷áíèå ÑÎÆ

Action of Cutting Fluid

- Penetration of the fluid to the interface is difficult because of high pressures and relative sliding speed.
- Therefore for the cutting fluid should have appropriate molecular size, good wetting properties and the right viscosity.



Shell Metal Working



Íàçíà÷áíèå ÑÎÆ

Key Parameters

Machining process:

Work piece material:

Tooling:


Cutting conditions:

Quality required:

- Turning, milling, etc.
- Machinability
- Tool material
- Shape or profile of tool
- Depth of cut
- Speed / Feed rate
- Application of fluid to cutting zone
- Surface quality
- Precision
- Corrosion protection

Shell Metal Working





Compact single spindle CNC lathe

Shell Metal Working



Ìđîöåññû ÎĐ

Ôđåçåđîâàíèå

- **Among the most versatile machine tools because of the variety of cutting operations.**
- **Metal chips are removed by rotating a circular multi-point tool which brings teeth into the workpiece one at a time as the work feeds into the cutter.**
- **Two basic types of milling machine:**
 - **Horizontal: cutter rotates on an horizontal arbor.**
 - **Vertical: cutter rotates in a vertical plane located in the column spindle.**
- **Other types of milling machine are available for special purposes such as the planer miller for heavy duty operations.**

Shell Metal Working



İđîöãññû ÎĐ

Ãëóáîêîâ ñâãđëáíèå, Ñâãđëáíèå è êîëüöåâîâ ñâãđëáíèå (1)

Deep hole drilling:

- the production of holes in which the length is 5 x up to 100 x the diameter
- The major difficulty is in removing the metal chips from, and maintaining coolant supply to, the cutting zone
- Three different deep drilling systems are employed to overcome this problem:
 - BTA system (Boring Trepanning Association)
 - Ejector system
 - Gun drilling

Shell Metal Working



İđiöãññû İİĐ

Ãëóáiêîâ ñâãđëáíèå, Ñâãđëáíèå è êîëüöåâîâ ñâãđëáíèå (2)

Boring:


- **Used to enlarge a hole to an exact size using a single point tool**
- **In horizontal boring, self supporting and guided boring bars with an inserted tool are used**

Trepanning:

- **similar to that of solid drilling except that a solid core of metal is produced**
- **Trepanning requires less power than solid drilling since less metal is removed in the process**


Shell Metal Working





Shell Metal Working





Đàçâđòûâàíèà

Shell Metal Working



İđiöãññû ÎĐ

Çóá÷àòûâ êîëãñà / ìàòîäû đãçàíëÿ

Several methods of gear making:

- Íàêàòêà: Favoured for high-volume production; continuous process where both workpiece (or blank) and the tool rotate and mesh as though it were an actual gear.
- Íàđãçàíèã: Often used for internal short gears. A rotary / reciprocating gear-shaped cutter is progressively fed into a rotating blank until the complete form of the gear is made. This is a non-continuous process exerting rapid intermittent tool load.
- Ôđãçãđîâàíèã: Employs a milling cutter shaped like the tooth form to be generated.

Shell Metal Working



Íðíöáññú ÍlÐ


Çóá÷àòûá êîëáñà / ìàòîäû ðåçàíèÿ

- **Gear Shaving**: Used as a finishing operation and used to improve surface finish and precision of gears formed by hobbing or shaping.
- **Gear grinding**: Used as a finishing operation. Two options:
 - **Continuous gear grinding**: Tool with the opposite form of the gear
 - **Teeth flank grinding**: Small, high speed and very precise tool moving in between gear teeth


Shell Metal Working




Gear Hobbing



Gear Cutting




Gear Shaping



External

Shell Metal Working





Worm Gear Cutting

Shell Metal Working



İđîöåññû ÎĐ

Đàçâåđòêà

- **The most severe of machining operations -**
- **Used to produce holes, grooves and slots in a variety of shapes and sizes.**
- **The broach is in effect a linear multi-tooth tool with spaced teeth which makes progressively deeper cuts.**
- **Broaching can machine complex shaped holes to precision limits in one pass**
- **Although the tool is expensive to manufacture, broaching can be a highly efficient process.**
- **Both horizontal and vertical broaching is possible.**

Shell Metal Working



Ìðîöåññû ÌÐ

Øëèôîâàíèå

- The grinding process is usually employed to impart a high standard of finish and accuracy to a machined component.
- Typical grinding processes include:
 - Surface grinding of flat surfaces - workpiece is clamped to a reciprocating, horizontal work table which is fed in small increments across the surface of the workpiece. Grinding wheel rotates at high speed and the wheel head remains stationary.
 - Cylindrical Grinding - Workpiece slowly rotating and driven between centres. The wheel rotates at high speed and on an axis parallel to that of the workpiece. The table is traversed longitudinally along the length of the workpiece to be ground.
 - Centreless Grinding - Similar to cylindrical grinding process, except the workpiece depends upon a regulating wheel running parallel to the grinding wheel for its location (see picture).
 - Other, more complicated types: flute grinding, creep feed grinding, tool grinding, etc.

Shell Metal Working



Īđiöãññû ĪĐ

Õííèíãîâàíèå, Ñóíãđôèíèøèđîâàíèå, Äîâîäèå

- **Honing**: special type of grinding, combined linear and rotating movement resulting in well defined “grid-like” roughness. Also called cross-grinding. E.g. the inside of hydraulic cylinders.
- **Super finishing**: also called external honing. Small oscillating movements of the tool. E.g. runway of ball bearings.
- **Lapping**: special type of grinding with mixture / paste of ceramic / diamond grains and oil. Polishing operation. E.g. Balls of ball bearing.

Shell Metal Working



İđîöåññû ÎĐ

İèëáíèå

- **Very common**
- **Three options:**
 - **Circular saw: very common**
 - **Belt saw: faster but takes more space**
 - **Oscillating saw: creates high friction on tool, high temperature**

Shell Metal Working



Îĩãðàöëè îáðàáíòêè ìåòàëëîâ

Operation Most severe

Internal Broaching, Surface or External broaching

Sawing

Tapping

Gear Cutting and Gear Shaving

Reaming, Deep Hole Drilling and Boring

Multiple Spindle Automatic Work

Milling and Form Turning

Planing and Shaping

Single Point Turning and Shallow Drilling

Least severe



Shell Metal Working



Õàðàéòáððèñòèèè ðáæ.èíñòðóíáíòà

Tool Materials	Machining operation and cutting speed range	Modes of tool wear or failure	Limitations
Carbon steel	Tapping, drilling, reaming (low speed)	Build-up, plastic deformation, abrasive wear, microchipping	Low hot hardness, limited hardenability, limited wear resistance
Low / medium alloy steels	Tapping, drilling, reaming (low speed)	Build-up, plastic deformation, abrasive wear, microchipping	Low hot hardness, limited hardenability, limited wear resistance
High-speed steels	Tapping, drilling, milling, broaching (medium speed)	Flank wear, crater wear	Low hot hardness, limited hardenability, limited wear resistance
Cemented carbides	Tapping, drilling, milling, broaching (medium speed)	Flank wear, crater wear	Cannot use at low speed due to cold welding of chips and microchipping
Coated carbides	Turning (medium to high speed)	Flank wear, crater wear	Cannot use at low speed due to cold welding of chips and microchipping
Ceramics	Turning (high speed to very high speed)	Depth-of-cut line notching, chipping, oxidation, graphitisation	Low strength, low thermalmechanical fatigue strength
Cubic boron nitride	Turning, milling (medium to high speed)	Depth-of-cut line notching, chipping, oxidation, graphitisation	Low strength, low chemical stability at higher temperatures
Carborundum	Grining, honing, super finishing and lapping	To much metal particles, abbrasive granulate limited	-
Diamond	Turning, milling and grinding (high to very high speed)	Chipping, oxidation, graphitisation	Low strength, low chemical stability at higher temperatures

Shell Metal Working



Òåõííëíãè÷ííñòü ìàòåðèàëíâ

Material	Tensile strength N/mm²
Brass	500
Steel	500 - 1300
Titanium alloys	1725
Aluminium alloys	700 - 1500 HB
Cast iron	1500 - 4500 HB

HB = Brinell Hardness

Shell Metal Working



Order of increasing ease of machinability

Magnesium alloys
Brass (Cu/Zn alloy)
Bronze (Cu/Sn alloy)
Aluminium alloys
Mild steel
Low / medium carbon steel
Wrought iron / cast iron alloys
Stainless steel
Nickel
Nickel / cobalt alloy
Titanium and titanium alloys

**Ease of
machinability**

Shell Metal Working



Spindle speed vs. Feed rate

(in metres/min) - Turning

Work Material	High-speed steel		Cemented carbide	
	Roughening	Finishing	Roughening	Finishing
Free Cutting steels	35	50	85	175
Low carbon steel	14	25	70	85
High carbon steel and tougher steels	12	17	60	85
Cast Iron	20	35	60	105
Aluminium alloys	105	170	210	350
Brass	70	115	175	285
Titanium alloys	9	15	35	65

The se figures are only an indication and may be significantly higher in some cases

Shell Metal Working



SHELL

İđîäóêòû Øåëë äëÿ
ìåòàëëñáðáíòêè

Shell Metal Working

03-Aug-22



ĨĪĐÒÔĂËÛ ÑÎÆ ØĂËË

ĨĐĂÈÌÓÙĂÑÒĂÀ ØĂËË

- Íîâúé ĩđòôăëü ÑÎÆ Øăëë
 - ÷ăòêàÿ êëàññèôèêàöèÿ ÑÎÆ ĩ ĩññòàâó è íàçíà÷áìèþ ĩđîäóêòîâ
 - óĭđîùáííúé ĩăáîđ ĩđîäóêòà
 - ññûëêè íà ìèđîâíé ĩîùò
 - èñĭĭëüçíâàíèà íîâăéøèö òăđĭĭēîâèé
 - ñîêðàùáíèà ÷èñëà ĩđîäóêòîâ
- Ĩđăèìóùăñòăî Øăëë ĩăđăă êĭĭéóđăíòàìè
 - øèđîêèé ĩôâàò òăđðèòîđèè - àèñòðèáüþòîđñêàÿ ñăòü
 - íàèàæáííàÿ ññòàìà ĩññòàâîê

Shell Metal Working

