

Flight Ops Summary

This document provides a quick overview of the operational impacts observed on the A320neo equipped with PW 1100G engines.

This list is not exhaustive and the published Airbus operational documentation (FCOM, QRH) remains the main reference.

CEO:Current Engine Option NEO: New Engine Option



Introduction



A320 Flight Crew Training





= Pilot qualified on A320 CEO and NEO







PW1100G


Library Democracy welf-

- High Bypass ratio
- Lower Noise Levels
- Complete system redesign (pylon, nacelle, bleed)

15% overall fuel burn reduction



A3200





A320neo







Modifications

Hardware modifications

ATA	Equipment
73	Engine Interface Unit (EIU)
24	Integrated Drive Generators (IDG)
30	Nacelle Anti-Ice (NAI)
36	Engine Bleed Air System (EBAS)

Software modifications


ATA	Equipment
22	Autoflight - FG & FAC
27	Flight Control - ELAC 98
31	Flight Warning Computer - FWC H2F8C

Minimum cange, Maximum commonality with A320 CEO



A320neo

Propulsion system






ATA 70

Powerplant




A320neo

Power Plant










ATA 70

Powerplant





Engine Primary Parameters





N1 instead of EPR

COOLING memo

ATA 70

Powerplant



A320neo

Dual Cooling





Powerplant

ATA 70


Dual Cooling function is armed when the DUAL COOLING pb-sw is ON. When armed, Cooling will be performed on both engines simultaneously.



A320neo

Dual Cooling

Dual Cooling function is available in a dedicated envelope of use depending on APU Performance and Oil temperature.





ATA 70

Powerplant





Integrated Drive Generator (IDG)



Derived from A340-500/600 for better reliability



ATA 24

_


Electrical Power





Nacelle Anti-Ice (NAI)

- <u>Two</u> Pressure Regulated & Shut off Valves (PRSOV) for better reliability and nacelle ice protection.
- Each valve is electrically controlled and pneumatically actuated to improve reliability and bleed control.





ATA 30

Ice & Rain Protection







Engine Bleed Air System (EBAS)

- New Engine Bleed Air System (EBAS) architecture.
- Electro-pneumatically valves (instead of fully pneumatically).







ATA 36

Pneumatic





Limitations (LIM)

Standard Operating Procedures (SOP)

Supplementary Procedures (SUP) Abnormal Procedures (ABN)



Wind and Autoland Limitations

- Take-off crosswind limitation:
 - **35kt** (38kt on A320ceo)

NOTE

The maximum certified crosswind value is an Airplane Flight Manual (AFM) limitation. It is an engine limitation.

Runway Surface Conditions	Maximum Crosswind for Takeoff (Gust included)	Maximum Crosswind for Landing (Gust included)
Damp		
Wet Up to 3 mm (1/8") of water	35kt	38kt

- Autoland Limitations:
 - Maximum Headwind................................ 20kt (30kt on A320ceo)

 - Maximum Tailwind................................ 5kt (10kt on A320ceo)
 - Airport elevation at or below 5750 feet



Limitations (LIM)



Engine Limitations

- **Engine Limitations:** Updated to take into account PW1100G specification.
 - RPM:
 - N1 max normal: 100% N1 max permissible: 105%
 - N2 max normal: 100% N2 max permissible: 105%
 - EGT Limit:
 - TOGA: 1083 ℃
 - MCT: 1043 °C
 - Starting: 1081°C
 - Oil Limits:
 - Minimum Oil Temperature prior to TO: 52 °C
 - Maximum Oil Temperature: 151°C
 - Minimum Oil Pressure: 65 PSI
 - Maximum Oil Pressure: 270 PSI

Note that red and amber oil pressure/temperature thresholds are not constant, and vary with the level of thrust.



Limitations (LIM)



Engine Limitations

- Starter Limits:
 - 3 consecutive start attempts
 - 35 sec between each cycle
 - after 3 cycles, a 15 min cooling period is necessary
 - No running engagement, when N2 is above 20%

NOTE

High Tailwinds (above 10kt) or crosswinds (above 35kt) may have an adverse effect on engine start. It may be necessary to reposition the aircraft into the wind.



Limitations (LIM)



Preliminary Cockpit Preparation

Preliminary Cockpit Preparation - Oil quantity check

- Minimum Oil quantity Value adapted to PW1100G:
 Check that oil quantity is at or above14 quarts. If OAT is colder than -30 °C check that oil quantity is at or above 16.5 quarts.
- If the engine oil quantity indication does not appear on the ENG SD page, set the ENG 1 and 2 FADEC GND PWR pb-sw on the overhead maintenance panel to ON. After the check of the engine oil quantity, set the ENG 1 and 2 FADEC GND PWR pb-sw to off.

Exterior Walkaround

Adapted to A320neo design





Engine Start

- Automatic engine start: Adaptation to PW1100G specificities:
 - Dry cranking information for flight crew awareness:

Memo **COOLING** displayed on the E/WD during automatic dry cranking commanded by FADEC depending on engine thermal state (see slide 10).

The dry cranking time is of approximately 2 min. During the dry cranking, the FADEC logic limits the maximum N2 around 10 %.

- Due to possible leakage from the ecology tank, FCOM asks to abort the start sequence if leak reported by ground crew during engine start. Maintenance action is due before the flight.
- When the FADEC detects a stall, applies an automatic recovery sequence without ECAM message.






Engine Start – Dual Cooling

The goal of the dual cooling function is to reduce the overall time to start both engines. This is achieved with the following sequence:

- Make sure that COOLING information is displayed on both engines.
- Select DUAL COOLING push button.



- Launch an auto start of one Engine (rotary selector to IGN and Master Lever ON), both Engines launch the cooling sequence.
- When both Engines complete the cooling sequence, the engine with Master Lever ON undertakes the start sequence.
- The second engine with Master Lever OFF is waiting for the Master Lever ON request to achieve its start, keeping in memory the cooling benefit (provided start is launched within 20mn).

Only available in automatic engine start and, therefore, will be reflected in **FCOM NORMAL SOP procedure – Automatic Engine Start**.





Engine Start

Engine start time longer than CEO

ON ECAM UPPER DISPLAY	ON ECAM LOWER DISPLAY	
N2 increases	Corresponding start valve inline.	
	Bleed pressure indication green.	
	Oil pressure increases.	
At approximately 18 % N2: - FF increases.	Indication of the active igniter (A or B).	
20 s (maximum) after fuel is on - EGT increases - N1 increases prior to 48 % N2.		
At approximately 55 % N2	Start valve crossline. Igniter indication off.	

Engine Idle Parameters (ISA sea level):

N1 about 19% N2 about 59% EGT about 600 °C FF about 270 kg/h







After Start









Ice Shedding

After Start – Ice shedding procedure

- Engine acceleration at a minimum of **60** % **of N1 at intervals not greater than 30 min.** There is no requirement to maintain the high thrust settings.
- If operating in conditions of freezing rain, freezing drizzle, freezing fog or heavy snow, the time intervals between engine accelerations shall not be greater than 10 min.
- If the ground surface conditions or the environment do not permit the above engine acceleration procedures during the taxi, then the 60 % N1 engine acceleration just before takeoff must be maintained for at least 2 min.





Parking

Parking

Caution note about brake vibrations

CAUTION	During parking, with brakes temperature above 200 °C, brakes vibrations may be
	experienced.
	In the case of severe vibrations, the flight crew should stop the aircraft and request
	towing.
	The flight crew must report any brakes vibrations phenomenon in the logbook.

The cooling period of 3 min before engine shutdown is required for NEO whereas it is recommended for CEO.
 Due to their design characteristics, NEO engines are more subject to degradation when routine cooldown times shorter than 3 min are applied. Therefore, flight crew <u>must</u> operate the engines at or near idle thrust for a cooling period of 3 min before shutdown to thermally stabilize the engines.






SUP-70 Power Plant

- Effect of the **dry cranking function** addressed in the following Supplementary Procedures (PRO-SUP):
 - Manual Engine Start

FADEC dry cranking even if manual engine start.

- Crossbleed Engine Start
- Engine ventilation (Dry Cranking)
- Removal of the Start Valve Manual Operation proc.
 Associated MEL item NO GO
- Air Conditioning during Automatic Engine Start:
 this procedure enables to recover air conditioning after automatic engine 2 start for passenger comfort.



Supplementary Procedures
SUP-70 Power Plant



SUP-93 GOP

- Single Engine Taxi-Out :
 - XBLEED remains closed to avoid the configuration of one Bleed supplying two Packs.
- Removal of the One PACK procedure because switching one PACK does NOT bring fuel economy benefit.



Supplementary Procedures

SUP-93 Green Operating Procedures



Abnormal Procedures

 New set of ECAM alerts due to enhanced monitoring of the engine (do <u>not</u> exist on A320ceo)

ENG 1(2) HIGH VIBRATION ENG 1(2) FAN COWL NOT CLSD

- <u>ENG</u> DUAL COOLING (function armed but not available i.e. out of the Dual Cooling envelope)
- Temporary Procedures to cover possible spurious ECAM triggering:

ANTI ICE ENG 1(2) VALVE CLSD



Abnormal Procedures (ABN)





Dispatch

Update of A320 MEL
Start Valve is a now "NO GO" item

No Significant change in the way to dispatch A320 NEO

Ground Ops unchanged



Minimum Equipment List



Performance

TOW around 3t more than CEO when performance limited. Higher thrust (3% to 7% increase vs CEO depending on OAT). Flexible temperature limited to ISA+50.

Landing performance improved. Increased Thrust Reverser efficiency.

Lower Noise Levels and emissions.

New version of FlySmart,
with
new interface and improved functionality



ATA 70. Powerplant

ATA 30. Nacelle Anti-Ice (NAI)

ATA 36. Engine Bleed Air System (EBAS)



GEN-General Information



DSC-Aircraft Systems



PRO-Procedures



LIM-Limitations





SOP & SUP □ No major changes

ABN □ New alerts

New FWC standard

ATA70, ATA24, ATA 36

No difference in Abnormal Maneuvers



GEN-General Information



DSC-Aircraft Systems



PRO-Procedures



LIM-Limitations





LIM 11. Weight & Center of Gravity limits

LIM 12. Environment Envelope – Wind Limitation

LIM 22. Auto Flight

LIM 70. Power Plant



GEN-General Information



DSC-Aircraft Systems



PRO-Procedures



LIM-Limitations





Updated Performance tables



GEN-General Information



DSC-Aircraft Systems



PRO-Procedures



LIM-Limitations





A320nes MEL

ATA 7x, 24, 30, 36

Update of Performance data

- MEL Entries
- MEL Items
- MEL Operational Procedures



The TCAS mode is an Auto Flight System mode which provides vertical guidance in case of a TCAS RA



- When a RA is triggered, the TCAS mode engages
- When "CLEAR OF CONFLICT", the TCAS mode disengages




AP/FD TCAS mode






When the TCAS mode arms, the FMA displays TCAS in blue.




TCAS mode arms, even if both APs, and both FDs are disengaged. In this case, the APs and FDs remain disengaged.

TCAS mode engaged



TCAS mode engages, even if both APs, and both FDs are disengaged.

- The AP engagement status does not change.
- If both FD bars are disengaged, the FD bars automatically engage.



AP/FD TCAS mode mode





Lateral mode

If the TCAS mode engages when a lateral mode is engaged, this lateral mode remains engaged.

Auto Thrust

When the TCAS mode engages, the A/THR SPEED/MACH mode engages.

Disengagement

When "CLEAR OF CONFLICT" sounds the TCAS mode disengages.
The AFS provides guidance toward the latest target altitude set on the FCU.
When the TCAS mode disengages one of the following modes engages:
V/S, ALT*, ALT, ALT CRZ* or ALT CRZ.



AP/FD TCAS mode





The TCAS mode is **not available**, when:

- The TCAS system is failed <u>NAV</u> TCAS FAULT
- The TCAS mode is failed <u>AUTO FLT TCAS MODE FAULT</u>
- The TCAS system is in TA mode
- FDs are inoperative.

The TCAS mode arming and engagement are **inhibited** when:

- The TA mode is manually selected
- The aircraft is below 900 ft radio height
- The EGPWS, WINDSHEAR or STALL warning is triggered.



AP/FD TCAS mode





(AP/FD) TCAS WARNINGS QRH procedure

This procedure is applicable ONLY to aircraft with AP/FD TCAS. Review QRH "Aircraft Configuration Summary" table to confirm AP/FD TCAS function on the specified aircraft.

If AP/FD TCAS mode is NOT installed or NOT available the "standard" TCAS Warnings procedure applies.

Only parts of the procedure are presented in the following slides.



AP/FD TCAS proc





■ Traffic Advisory (TA) alert:

If the A/THR is off:

A/THRON

The flight crew should set the A/THR to ON to avoid the triggering of the <u>AUTO FLT</u> A/THR LIMITED alert at the A/THR activation, in the case of a RA.

Do not perform a maneuver based on a TA alone.



AP/FD TCAS proc (TA)





- Resolution Advisory (RA) alert
 - If TCAS flight guidance mode is available

The flight crew applies this procedure, when a RA is triggered, and the TCAS mode engages. The TCAS mode follows the RA orders.

If AP OFF

FD ORDERs......FOLLOW

The AP can be engaged.

VERTICAL SPEED......MONITOR

If a preventive RA was triggered: Check that the vertical speed remains out of the red area of the vertical speed scale.

If a corrective RA was triggered: Check that the vertical speed gets out of the red area, and remains in the green area of the vertical speed scale.

CAUTION

If for any reason during an RA, the aircraft vertical speed does not reach the green area of the vertical speed scale, the Pilot Flying (PF) should disconnect the AP, and override the FD orders, in order to lead the aircraft vertical speed out of the red area of the vertical speed scale. If necessary, the PF must use the full speed range between Vamax and Vmax



AP/FD TCAS proc (RA)





When "CLEAR OF CONFLICT" aural alert sounds

If engaged, the TCAS mode disengages

AP/FD	MONITOR/FOLLOW
ATC	NOTIFY
LATERAL AND VERTICAL GUIDANCE	ADJUST

The flight crew should engage an appropriate vertical mode, or adjust the vertical speed target, in accordance with the latest ATC clearance.

SPEED.......ADJUST


The flight crew should adjust the speed target, and revert to managed speed, as appropriate.



AP/FD TCAS proc (RA)









AP/FD TCAS proc





Refer to FCOM and review:



DSC-Aircraft Systems

C-22_30-70-85 TCAS mode



-ABN-34 TCAS Warnings

Refer to QRH and review: ABN-34 TCAS WARNINGS



AP/FD TCAS proc (RA)





A320 Air Astana

Registration: P4-KBH

MSN: 7124 Model: 320-271N

