MY21 exterior plastic tooling delivery and launch

Global target: SORP - W2052 (21.12.2020)

Problem: late tooling delivery to Region Volga

Reason: late design freeze, unplanned time for graining repair and mold hot running system breakdown for rear door moldings

Counter measure: to split and speed up tooling delivery: 1st batch 2 trucks (left on 30.09) and 2nd batch 5 trucks (plan 12.10) + rear door 112 mold (plan 19.10)

Stages	October					November				December					January	
	40	4 1	42	43	44	45	46	47	48	49	50	51	52	53	1	2
Rear door moldings tooling repair and sample production		1														
Rear door moldings sample delivery																
32 samples delivery (T-3 2)																
Parts final acceptance (T-3 2, exept rear door moldings)		I														
Tooling packaging																
Tooling transfer and cust.cleareance batch_1 (2 trucks)		>														
Tooling transfer and cust.cleareance batch_2 (5 trucks)		<														
Tooling transfer and cust.cleareance batch_3 (rear door moldings)																
Tooling mounting on suppliers side																
Tooling trial run		•														
Parts measurement		0														
Lab tests		II														
PPAP document's providing		1														
Master samples agreed		⋖														
SORP injection parts		z														
SORP painted parts		1_														
SORP parts delivery to LADA WEST TLT		II														
SORP		U														

MY21 exterior plastic tooling delivery and launch





